

Vehicle Description

DATE INSPECTED: 21/03/2017

2016 Porsche Macan 95B GTS Wagon 5dr PDK 7sp AWD 3.0TT INSPECTION POINTS CHECKED: 150+

VIN	WP1ZZZ95ZHLB64294
Engine Number	009118
Compliance Date	10/2016
Build Date	2016
Odometer Reading	4,492
Registration Number	AKV904
Registration Expiry	29/11/2017
Reason for inspection	Seller



Overall Rating



GOOD

Engine Bay



GOOD

Interior




GOOD

Exterior



GOOD



Road Test



GOOD

Tyres, Wheels & Brakes



GOOD

The inspection is visual and non-mechanical only. Refer to terms and conditions on last page for further details and explanation of ratings.

Graphic is not actual vehicle

Interior



Seats

All seats in good condition at time of inspection



Seat Belts

All seatbelt condition and operation, ok at time of inspection

NA

Other Trims



Radio

Standard radio equipment fitted to vehicle and operation ok at time of inspection



Rear Window Demister

Rear window demister display indicating system functioning ok at time of inspection



Air Conditioning

Air conditioning is getting cold, operation satisfactory at time of inspection



Heater Demister

All heater controls, functions and direction controls working at time of inspection

★★★★★ GOOD

★★★★☆ FAIR

★★☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED



Washers & Wipers

All wipers controls and functions ok at time of inspection



Horn

Horn operation and sound audible at time of inspection



Doors, Locks & Hinges

All door, locks and hinges in good condition



Window Operation

All electric window operation and functions ok at time of inspection



Dash Warning Lights & Gauges

No warning lights displayed on dash at time of inspection, scan tool test indicating no Stored DTC's at time of inspection



All Lights

All lights working and lenses are in good condition at time of inspection.

NA

Other

★★★★★ GOOD

★★★☆☆ FAIR

★☆☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED

Interior Visual Details



Interior Visual Details



Exterior



Rust

No rust sighted at time of inspection



Body Repairs

Paint depth consistency stable, gauge indicating no repairs have been carried out to vehicle



Glass & Mirrors

All glass and mirrors in good condition



Sunroof, Aerial & Convertible

Sunroof operations and functions ok at time of inspection Aerial reception ok indicating system ok at time of inspection



Frames & Members

Frames and members are in good condition



Under Body Parts

Ok at time of inspection



Front Suspension

Ok at time of inspection

★★★★★ GOOD

★★★★☆ FAIR

★★☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED



Rear Suspension

Ok at time of inspection



Steering Components

Ok at time of inspection



Transmission Housing

Vehicle is fitted with an automatic transminssion, no external leaks or damage to report at time of inspection



Exhaust

Exhaust in good condition at time of inspection



Differential

No external leaks or damage to report at time of inspection



Drive Shafts

Drive shafts and cv boots in good working order at time of inspection

NA

Other

★★★★★ GOOD

★★★☆☆ FAIR

☆☆☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED

Exterior Visual Details



Exterior Visual Details



Engine Bay



Noise

No unusual noises to report at time of inspection



Fluid Level

All accessible fluid levels checked are ok at time of inspection



Fluid Leaks

No fluid leaks to report at time of inspection



Mountings

Ok at time of inspection



Hoses & Pipes

Ok at time of inspection



Water Pump & Fan

Ok at time of inspection



Ignition System

Ignition system operation ok at time of inspection

★★★★★ GOOD

★★★☆☆ FAIR

☆☆☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED



Fuel System

Fuel system ok at time of inspection



Battery

Battery ok at time of inspection and is securely mounted



Radiator & Cap

No leaks to report at time of inspection



Drive Belt & Pulleys

Drive belt and pulley condition ok at time of inspection



Brake Booster

Brake booster operation ok at time of inspection



Master Cylinder Pressure & A.B.S. Function

Ok at time of inspection

NA

Other

★★★★★ GOOD

★★★★☆ FAIR

★★☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED

Engine Bay Visual Details



Engine Bay Visual Details



Engine Bay Visual Details



Tyres, Wheels & Brakes



Tyres

All tyres are in as new condition



Wheel Rims

All rims in good condition, no markings on them at time of inspection



Spare Tyre & Rim

Spare tyre present and secure at time of inspection



Brake Hose Callipers & Pipes

Ok at time of inspection



Brake Pads

Ok at time of inspection



Brake Discs

Ok at time of inspection

NA

Brake Linings

★★★★★ GOOD

★★★☆☆ FAIR

★☆☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED

NA Wheel Cylinders

NA Brakes and Drums



Park Brake

Electric Park brake holding and operation ok at time of inspection



Wheel Bearings

Ok at time of inspection

NA Other

★★★★★ GOOD

★★★★☆ FAIR

★★☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED

Tyres, Wheels & Brakes Visual Details



Tyres, Wheels & Brakes Visual Details



Road Test



Ease of Starting & Idle

Vehicle starting ok and idle remained consistent throughout inspection



Engine Noise

No unusual noises to report at time of inspection



Engine Performance

Engine performance excellent at time of inspection



Exhaust Smoke & Emissions

No smoke was noticeable throughout inspection



Gearbox Drive Operation

Automatic transmission shift and operation is smooth and satisfactory taken into consideration the age and kms



Differential

No differential issues observed during test drive.



Steering & Suspension

★★★★★ GOOD

★★★★☆ FAIR

★★☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED



Brake Operation

Steering smooth and consistent in operation, ok at time of inspection



Speedo

Speedo operating ok at time of inspection



Cruise Control

Cruise control operation and functions ok at time of inspection



4 Wheel Drive

Ok at time of inspection

NC

Camshaft & Drive Belt



Owner's Manual & Service Intervals

Owners manual and service books present at time of inspection

NA

Other

★★★★★ GOOD

★★★☆☆ FAIR

★☆☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED

Overall



General Comments

Vehicle is in good condition for the age and klms, car presents it self very well has been cared for and kept in great condition. Vehicle shows no signs of having body repairs carried out. Mechanically the vehicle is in as new condition.

Ratings

★★★★★	GOOD	Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.
★★★★☆	FAIR	Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.
★★★☆☆	POOR	Item found not to be in working order and/or major signs of damage and/or wear & tear.
NA	NOT APPLICABLE	Vehicle does not have this item fitted/installed.
NC	NOT CHECKED	Potential defect observed but item not further investigated/dismantled.

Disclaimer

- (a) The inspection is VISUAL and non-mechanical only and RedBook Inspect will not be responsible for any defects that are latent discovered which were not visually apparent during the inspection. The inspection will cover the vehicle's exterior, interior, engine compartment, tyres and wheels, brakes, under body and a road test where possible. The inspection will specifically not cover the items set out below. No removal of parts or components is undertaken during the inspection process. You acknowledge that while RedBook Inspect's inspectors use accepted methods for fault detection, these methods will not necessarily identify all faults with a vehicle. You should consider the age and condition of the vehicle at the time of inspection and any Report should be reviewed in this context. Vehicles are only road tested to speed limit of local area.
- (b) The Report provided by RedBook Inspect to you is only current as at the time it is issued. It is a buyer's responsibility to conduct a visual inspection of the vehicle at the point of sale as RedBook Inspect can only advise on the condition of the vehicle at the time of inspection. The Report is not a roadworthy certificate and cannot be used as a roadworthy. You acknowledge that RedBook Inspect does not check for any manufacturer recall notices and you should check that the vehicle is not subject to a recall notice.
- (c) RedBook Inspect will not be responsible for the terms of any transaction between any persons in relation to any vehicle inspected by RedBook Inspect or for resolving any dispute between any persons regarding any transaction.
- (d) Subject to all applicable laws, RedBook Inspect does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the Report or the fitness of the information contained in the Report for any purpose intended by you. To the full extent permitted by the law, RedBook Inspect will only be liable to you: (i) pursuant to any guarantee, right or contractual term that arises, is created or is implied by operation of law and that cannot be excluded PROVIDED THAT to the full extent permitted by law, any such liability of RedBook Inspect is limited, at RedBook Inspect's option, to (A) replacing or repairing the relevant goods (B) supplying goods equivalent to the relevant goods (C) supplying the relevant services again; or (D) paying the cost of such replacement, repairs or supply, subject always to subclause (g) below; or (ii) if Your claim arises from or in connection with any deliberate breach of these terms and conditions or fraud by RedBook Inspect.
- (e) Except to the extent that liability cannot be excluded, RedBook Inspect, will not be liable to you for claims arising out of or in connection with your access and use of the this Report whether arising in contract, tort (including negligence), indemnity, strict liability, breach of warranty or statute.
- (f) To the full extent permitted by law, RedBook Inspect will not be liable to you for loss of use, production, profit, revenue, business, data, contractor anticipated savings or for delay or for any financing costs or increase in operating costs or any economic loss for any indirect or consequential loss or damage.
- (g) Your use of this Inspection Report is subject to the RedBook Inspect Service Terms available at <http://www.redbookinspect.com.au/terms-of-service>

RedBook Inspect does not check the following items

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks
- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems