

Vehicle Description

DATE INSPECTED: 12/12/2017

Mazda 2

VIN JM0DE10Y180116617
 Engine Number -
 Compliance Date 05/08
 Build Date 2008
 Odometer Reading 161478
 Registration Number BGI86J
 Registration Expiry 12/12/2017
 Reason for inspection Seller



Overall Rating



FAIR

Engine Bay



GOOD

Interior




GOOD

Exterior



FAIR



Road Test



GOOD

Tyres, Wheels & Brakes



FAIR

The inspection is visual and non-mechanical only. Refer to terms and conditions on last page for further details and explanation of ratings.

Graphic is not actual vehicle

Interior



Seats

General wear/marks to seats and trims.



Seat Belts

General wear to see belts and components.



Other Trims

Gear shift knob trim slightly loose. Mirror adjustment switch slightly loose. General wear to ignition key.



Radio



Rear Window Demister



Air Conditioning



Heater Demister

★★★★★ GOOD

★★★★☆ FAIR

★★☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED

★★★★★ Washers & Wipers

★★★★★ Horn

★★★★★ Doors, Locks & Hinges

★★★★★ Window Operation

★★★★★ Dash Warning Lights & Gauges


★★★☆☆ All Lights
Driver-side park light globe inoperative – replace. Some minor cracking starting to form on passenger-side headlight lens.

NA Other

Interior Visual Details



Interior Visual Details



Exterior



★★★★★ Rust



Body Repairs

Some cosmetic paint repairs to various parts of people all of the body. Minor marks, chips, dents and scratches to various parts of vehicle.



Glass & Mirrors

Minor chips and scratches to windscreen.

NA Sunroof, Aerial & Convertible



Frames & Members



Under Body Parts



Front Suspension

General wear to suspension and bushes consistent with age and kilometres travelled.



Rear Suspension

General wear to suspension and bushes consistent with age and kilometres travelled.



Steering Components

General wear to steering components consistent with age and kilometres travelled.



Transmission Housing

General wear to transmission, clutch and drivetrain components consistent with age and kilometres travelled.



Exhaust

General wear consistent with age and kilometres travelled.



Differential



Drive Shafts

General wear to drive shafts and boots.

NA

Other

Exterior Visual Details



Exterior Visual Details



Engine Bay



★★★★★ Noise

★★★★★ Fluid Level

★★★★☆☆ Fluid Leaks
No evidence of major fluid leaks at time of inspection. Very minor dampness around lower engine/transmission areas.

★★★★★ Mountings
General wear to mounts.

★★★★★ Hoses & Pipes
General wear to hoses and pipes.

★★★★★ Water Pump & Fan
General wear to water pump and fan components.

★★★★★ Ignition System

★★★★★ Fuel System

★★★★★ Battery

Battery starting vehicle fine and testing good at time of inspection. Battery near new.

★★★★★ Radiator & Cap

General wear to radiator and components.

★★★★★ Drive Belt & Pulleys

General wear to drive belts and pulleys.

★★★★★ Brake Booster

★★★★★ Master Cylinder Pressure & A.B.S. Function

NA Other

Engine Bay Visual Details



Engine Bay Visual Details



RedBook
INSPECT



RedBook
INSPECT

Engine Bay Visual Details



Tyres, Wheels & Brakes



Tyres

General wear to all tyres. Minor marks to outside side wall of tyres.



Wheel Rims

Minor marks and scratches to wheel rims.



Spare Tyre & Rim

NA

Brake Hose Callipers & Pipes



Brake Pads

General wear to brake pads.



Brake Discs

General wear to brake discs.

NC

Brake Linings

NC Wheel Cylinders

NC Brakes and Drums

★★★★★ Park Brake
General wear consistent with age and kilometres travelled.

★★★★★ Wheel Bearings
General wear consistent with age and kilometres travelled.

NA Other

Tyres, Wheels & Brakes Visual Details



Tyres, Wheels & Brakes Visual Details



Road Test



★★★★★ Ease of Starting & Idle

★★★★★ Engine Noise

★★★★★ Engine Performance
General wear to engine and components consistent with age and kilometres travelled. Note: limited road test possible due to road conditions and local speed limits as per usual.

★★★★★ Exhaust Smoke & Emissions

★★★★★ Gearbox Drive Operation

★★★★★ Differential

★★★★★ Steering & Suspension

★★★★★ Brake Operation

★★★★★ Speedo

NA Cruise Control

NA 4 Wheel Drive

NC Camshaft & Drive Belt

★★★★☆☆ Owner's Manual & Service Intervals
Log book sighted. Majority of services logged in book.

NA Other

Overall



General Comments

Key findings include: Driver-side front park light globe inoperative. Optional extras include: GPS (n) Reverse Camera (n) - Front or rear sensors (n) Leather seats (n) - Wheel rim size 16" Floor mats (y) - Cruise control (n) Tow bar (n) - Sunroof/moonroof (n) Auto/manual transmission (manual) - Driver assist (n) ABS (y) Additional photos referenced in this report to follow by email. Additional photos/email forms part of this report. General marks and wear to various parts of interior/exterior. General wear to engine, transmission, suspension/bushes and drivetrain, consistent with age and kilometres travelled. General wear to doors, locks and hinges/windows and various components to be expected with age/kilometres travelled. General wear to brake pads and brake discs. Vehicle in fair condition reflecting age and Km's traveled. One key provided, log book sighted.

Ratings

★★★★★	VERY GOOD	Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.
★★★★☆	GOOD	
★★★☆☆	FAIR	Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.
★★☆☆☆	POOR	
★☆☆☆☆	VERY POOR	Item found not to be in working order and/or major signs of damage and/or wear & tear.
NA	NOT APPLICABLE	Vehicle does not have this item fitted/installed.
NC	NOT CHECKED	Potential defect observed but item not further investigated/dismantled.

Disclaimer

- (a) The inspection is VISUAL and non-mechanical only and RedBook Inspect will not be responsible for any defects that are latent discovered which were not visually apparent during the inspection. The inspection will cover the vehicle's exterior, interior, engine compartment, tyres and wheels, brakes, under body and a road test where possible. The inspection will specifically not cover the items set out below. No removal of parts or components is undertaken during the inspection process. You acknowledge that while RedBook Inspect's inspectors use accepted methods for fault detection, these methods will not necessarily identify all faults with a vehicle. You should consider the age and condition of the vehicle at the time of inspection and any Report should be reviewed in this context. Vehicles are only road tested to speed limit of local area.
- (b) The Report provided by RedBook Inspect to you is only current as at the time it is issued. It is a buyer's responsibility to conduct a visual inspection of the vehicle at the point of sale as RedBook Inspect can only advise on the condition of the vehicle at the time of inspection. The Report is not a roadworthy certificate and cannot be used as a roadworthy. You acknowledge that RedBook Inspect does not check for any manufacturer recall notices and you should check that the vehicle is not subject to a recall notice.
- (c) RedBook Inspect will not be responsible for the terms of any transaction between any persons in relation to any vehicle inspected by RedBook Inspect or for resolving any dispute between any persons regarding any transaction.
- (d) Subject to all applicable laws, RedBook Inspect does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the Report or the fitness of the information contained in the Report for any purpose intended by you. To the full extent permitted by the law, RedBook Inspect will only be liable to you: (i) pursuant to any guarantee, right or contractual term that arises, is created or is implied by operation of law and that cannot be excluded PROVIDED THAT to the full extent permitted by law, any such liability of RedBook Inspect is limited, at RedBook Inspect's option, to (A) replacing or repairing the relevant goods (B) supplying goods equivalent to the relevant goods (C) supplying the relevant services again; or (D) paying the cost of such replacement, repairs or supply, subject always to subclause (g) below; or (ii) if Your claim arises from or in connection with any deliberate breach of these terms and conditions or fraud by RedBook Inspect.
- (e) Except to the extent that liability cannot be excluded, RedBook Inspect, will not be liable to you for claims arising out of or in connection with your access and use of the this Report whether arising in contract, tort (including negligence), indemnity, strict liability, breach of warranty or statute.
- (f) To the full extent permitted by law, RedBook Inspect will not be liable to you for loss of use, production, profit, revenue, business, data, contractor anticipated savings or for delay or for any financing costs or increase in operating costs or any economic loss for any indirect or consequential loss or damage.
- (g) Your use of this Inspection Report is subject to the RedBook Inspect Service Terms available at <http://www.redbookinspect.com.au/terms-of-service>

RedBook Inspect does not check the following items

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks
- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems