

Vehicle Description

DATE INSPECTED: 26/03/2018

2013 Mazda CX-5 Maxx Sport KE Wagon 5 Door 2.2L Turbo Diesel 6 Spd Auto

VIN	JMOKE102100234527
Engine Number	SH30386177
Compliance Date	12/2013
Build Date	2013
Odometer Reading	85172
Registration Number	1AV7KH
Registration Expiry	21/04/2018
Reason for inspection	Pre-Purchase



Overall Rating



GOOD

Engine Bay



GOOD

Interior




GOOD

Exterior



GOOD



Road Test



GOOD

Tyres, Wheels & Brakes



GOOD

The inspection is visual and non-mechanical only. Refer to terms and conditions on last page for further details and explanation of ratings.

Graphic is not actual vehicle

Interior



Seats
Ok at time of inspection



Seat Belts
Ok at time of inspection



Other Trims
Minor scuffs on some interior trims



Radio
Operating and ok at time of inspection



Rear Window Demister
Ok at time of inspection



Air Conditioning
Operating and ok at time of inspection



Heater Demister
Ok at time of inspection

★★★★★ GOOD

★★★★☆ FAIR

★★☆☆☆ POOR

NA NOT APPLICABLE

NC NOT CHECKED



Washers & Wipers

Ok at time of inspection



Horn

Ok at time of inspection



Doors, Locks & Hinges

General wear consistent with age and kilometers travelled Ok at time of inspection



Window Operation

Ok at time of inspection



Dash Warning Lights & Gauges

Ok at time of inspection



All Lights

Ok at time of inspection



Other

Vehicle equipped with: Cloth interior Carpet mats GPS Reverse camera 17" Alloy wheels Vehicle not equipped with: Front and rear park assist Drivers assist

Interior Visual Details



Interior Visual Details



Exterior



Rust

No rust evident at time of inspection.



Body Repairs

No body repairs evident according to depth gauge readings. Minor scratches on rear bumper bar Dent evident on front passenger door Damage on left side mirror



Glass & Mirrors

Windscreen is ok at time of inspection.



Sunroof, Aerial & Convertible

Aerial operating and ok at time of inspection.



Frames & Members

General wear consistent with age and kilometers travelled Ok at time of inspection



Under Body Parts

Ok at time of inspection



Front Suspension

General wear consistent with age and kilometers travelled Ok at time of inspection



Rear Suspension

General wear consistent with age and kilometers travelled Ok at time of inspection



Steering Components

General wear consistent with age and kilometers travelled Ok at time of inspection



Transmission Housing

Ok at time of inspection



Exhaust

Ok at time of inspection



Differential

Ok at time of inspection



Drive Shafts

General wear consistent with age and kilometers travelled Ok at time of inspection




Other

Exterior Visual Details



Exterior Visual Details



Engine Bay



Noise

Engine bay noise consistent with age and kilometres travelled.



Fluid Level

All fluid levels ok at time of inspection



Fluid Leaks

Full under tray fitted to underside of vehicle No fluid leaks evident at time of inspection Inspected via side access points



Mountings

General wear consistent with age and kilometers travelled Ok at time of inspection



Hoses & Pipes

Ok at time of inspection



Water Pump & Fan

Ok at time of inspection



Ignition System

Ok at time of inspection



Fuel System

Ok at time of inspection



Battery

Tested battery for charge and durability Ok at time of inspection



Radiator & Cap

Ok at time of inspection



Drive Belt & Pulleys

Ok at time of inspection



Brake Booster

Ok at time of inspection



Master Cylinder Pressure & A.B.S. Function

Ok at time of inspection



Other

No diagnostic fault codes found at time of inspection Refer to photos attached


Engine Bay Visual Details



Engine Bay Visual Details



Engine Bay Visual Details



Tyres, Wheels & Brakes



Tyres

Ok at time of inspection



Wheel Rims

Ok at time of inspection



Spare Tyre & Rim

Ok at time of inspection



Brake Hose Callipers & Pipes

Ok at time of inspection



Brake Pads

Brake pads wearing consistant with age and kilometers travelled Ok at time of inspection



Brake Discs

Brake discs wearing consistant with age and kilometers travelled Ok at time of inspection

NA

Brake Linings

NA Wheel Cylinders

NA Brakes and Drums

★★★★★ Park Brake
Ok at time of inspection

★★★★★ Wheel Bearings
Ok at time of inspection

★★★★★ Other

Tyres, Wheels & Brakes Visual Details



Tyres, Wheels & Brakes Visual Details



Road Test



Ease of Starting & Idle

Ok at time of inspection



Engine Noise

Ok at time of inspection



Engine Performance

Ok at time of inspection



Exhaust Smoke & Emissions

Ok at time of inspection



Gearbox Drive Operation

Ok at time of inspection



Differential

Ok at time of inspection



Steering & Suspension

Ok at time of inspection



Brake Operation

Ok at time of inspection



Speedo

Ok at time of inspection



Cruise Control

Ok at time of inspection



4 Wheel Drive

Ok at time of inspection



Camshaft & Drive Belt

Engine fitted with a timing chain Ok at time of inspection



Owner's Manual & Service Intervals

Owners manual present at time of inspection Service book present at time of inspection Service history is up to date



Other

Overall



General Comments

1 key presented at time of inspection (2 available) Service history is up to date All servicing has been done by genuine Mazda dealerships
Vehicle test drove well and kept in good condition

Ratings

★★★★★	VERY GOOD	Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.
★★★★☆	GOOD	
★★★☆☆	FAIR	Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.
★★☆☆☆	POOR	
★☆☆☆☆	VERY POOR	Item found not to be in working order and/or major signs of damage and/or wear & tear.
NA	NOT APPLICABLE	Vehicle does not have this item fitted/installed.
NC	NOT CHECKED	Potential defect observed but item not further investigated/dismantled.

Disclaimer

- (a) The inspection is VISUAL and non-mechanical only and RedBook Inspect will not be responsible for any defects that are latent discovered which were not visually apparent during the inspection. The inspection will cover the vehicle's exterior, interior, engine compartment, tyres and wheels, brakes, under body and a road test where possible. The inspection will specifically not cover the items set out below. No removal of parts or components is undertaken during the inspection process. You acknowledge that while RedBook Inspect's inspectors use accepted methods for fault detection, these methods will not necessarily identify all faults with a vehicle. You should consider the age and condition of the vehicle at the time of inspection and any Report should be reviewed in this context. Vehicles are only road tested to speed limit of local area.
- (b) The Report provided by RedBook Inspect to you is only current as at the time it is issued. It is a buyer's responsibility to conduct a visual inspection of the vehicle at the point of sale as RedBook Inspect can only advise on the condition of the vehicle at the time of inspection. The Report is not a roadworthy certificate and cannot be used as a roadworthy. You acknowledge that RedBook Inspect does not check for any manufacturer recall notices and you should check that the vehicle is not subject to a recall notice.
- (c) RedBook Inspect will not be responsible for the terms of any transaction between any persons in relation to any vehicle inspected by RedBook Inspect or for resolving any dispute between any persons regarding any transaction.
- (d) Subject to all applicable laws, RedBook Inspect does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the Report or the fitness of the information contained in the Report for any purpose intended by you. To the full extent permitted by the law, RedBook Inspect will only be liable to you: (i) pursuant to any guarantee, right or contractual term that arises, is created or is implied by operation of law and that cannot be excluded PROVIDED THAT to the full extent permitted by law, any such liability of RedBook Inspect is limited, at RedBook Inspect's option, to (A) replacing or repairing the relevant goods (B) supplying goods equivalent to the relevant goods (C) supplying the relevant services again; or (D) paying the cost of such replacement, repairs or supply, subject always to subclause (g) below; or (ii) if Your claim arises from or in connection with any deliberate breach of these terms and conditions or fraud by RedBook Inspect.
- (e) Except to the extent that liability cannot be excluded, RedBook Inspect, will not be liable to you for claims arising out of or in connection with your access and use of the this Report whether arising in contract, tort (including negligence), indemnity, strict liability, breach of warranty or statute.
- (f) To the full extent permitted by law, RedBook Inspect will not be liable to you for loss of use, production, profit, revenue, business, data, contractor anticipated savings or for delay or for any financing costs or increase in operating costs or any economic loss for any indirect or consequential loss or damage.
- (g) Your use of this Inspection Report is subject to the RedBook Inspect Service Terms available at <http://www.redbookinspect.com.au/terms-of-service>

RedBook Inspect does not check the following items

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks
- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems